



Large Solino Garden Thermometer With Solar Light 109cm

Product Images



Short Description

The Solino Garden thermometer is made with plexiglass and metal, and can be put in to the ground using the mounting spike.

The unit has a solar power panel on the top, which collects energy during the day and is then able to power

up a light once night time falls.

The unit can be left outside constantly, and is fully weather resistant.

- Temperature Range: -30°C to +50°C
- Measurement: Temperature Range: °C
- Dimenions: L 109. x W 138mm
- Battery: Solar Powered with 2 x AAA rechargeable (included)
- Warranty: 1 Year
- Manufacturer: TFA

Description

The Solino Garden thermometer is made with plexiglass and metal, and can be put in to the ground using the mounting spike.

The unit has a solar power panel on the top, which collects energy during the day and is then able to power up a light once night time falls.

The unit can be left outside constantly, and is fully weather resistant.

- Temperature Range: -30°C to +50°C
- Measurement: Temperature Range: °C
- Dimenions: L 109. x W 138mm
- Battery: Solar Powered with 2 x AAA rechargeable (included)
- Warranty: 1 Year
- Manufacturer: TFA

Additional Information

Brand	TFA Dostmann
Humidity	no
Temperature	yes
Temperature Sensor	no
Hair Hygrometer	no
HACCP Compliant	no
Auto Switch Off	no
Hold Function	no
Probe Type	no
Warranty	1 Year
Calendar	no
Min/Max Readings	no
Humidity Sensor	no
Clip-On	no
Humidity Range	no
Weatherproof	yes
Waterproof	no
Solar Light	yes
Probe Temperature	no
Temperature Resolution	+/- 1°C
Calibration	Can Not Be Calibrated
Dew Point	no
Comfort Level Indicator	no
Size : Depth	13.8cm
Outdoor Temperature	yes
Moon Phase	no

Packlight	20
Backlight	no
Humidity Accuracy	no
Humidity Resolution	no
Indoor Humidity	no
Clock	no
Transmission Range	no
Transmission Frequency	no
Temperature Range	-30 to 50°C
Temperature Accuracy	+/- 1°C
Size : Height	109cm
Size : Width	13.8cm
Size : Width Measuring Units	13.8cm °C
Measuring Units	°C
Measuring Units PC Connection	°C no
Measuring Units PC Connection Touch Screen	°C no no
Measuring Units PC Connection Touch Screen Min/Max Reset	°C no no no
Measuring UnitsPC ConnectionTouch ScreenMin/Max ResetDew Point Alarm	°C no no no no no no
Measuring UnitsPC ConnectionTouch ScreenMin/Max ResetDew Point AlarmHigh/Low Humidity Alarm	°C no no no no no no no
Measuring UnitsPC ConnectionTouch ScreenMin/Max ResetDew Point AlarmHigh/Low Humidity AlarmHigh/Low Temp Alarm	°C no no