




# Stainless Steel Compost Thermometer 41cm

## Product Images



## Short Description

---

Successful composting requires heat, air and moisture; otherwise a fouling decay process will start producing an unpleasant smell and substances. You can check the normal rotting process in the course of time with the compost thermometer.

1st Phase: Disintegration control temperature 50-80 °C (at least 2-3 weeks)

2nd Phase: Conversion to humus control temperature 40°C (at most 9 months)

- Temperature Range: -10°C to 90°C
- Penetration probe: 410mm
- Measurement: °C
- Dimensions: L 400 x W 50mm
- Warranty: 1 Year
- Manufacturer: TFA

## Description

---

Successful composting requires heat, air and moisture; otherwise a fouling decay process will start producing an unpleasant smell and substances. You can check the normal rotting process in the course of time with the compost thermometer.

1st Phase: Disintegration control temperature 50-80 °C (at least 2-3 weeks)

2nd Phase: Conversion to humus control temperature 40°C (at most 9 months)

- Temperature Range: -10°C to 90°C
- Penetration probe: 410mm
- Measurement: °C
- Dimensions: L 400 x W 50mm
- Warranty: 1 Year
- Manufacturer: TFA

## Additional Information

Brand	TFA Dostmann
Humidity	no
Temperature	yes
Temperature Sensor	no
Hair Hygrometer	no
HACCP Compliant	no
Auto Switch Off	no
Hold Function	no
Probe Type	Penetration Probe
Warranty	1 Year
Calendar	no
Min/Max Readings	no
Humidity Sensor	no
Clip-On	no
Humidity Range	no
Weatherproof	yes
Waterproof	no
Solar Light	no
Probe Temperature	yes
Temperature Resolution	+/- 1°C
Calibration	Can Not Be Calibrated
Dew Point	no
Comfort Level Indicator	no
Size : Depth	5cm
Outdoor Temperature	yes
Moon Phase	no

Backlight	no
Humidity Accuracy	no
Humidity Resolution	no
Indoor Humidity	no
Clock	no
Transmission Range	no
Transmission Frequency	no
Temperature Range	-10 to 90°C
Temperature Accuracy	+/- 1°C
Size : Height	41cm
Size : Width	5cm
Measuring Units	°C
PC Connection	no
Touch Screen	no
Min/Max Reset	no
Dew Point Alarm	no
High/Low Humidity Alarm	no
High/Low Temp Alarm	no
Outdoor Humidity	no
Indoor Temperature	no